

GRANNY'S POOL TO MAIN BEACH SITE PHOTOGRAPHS

Please note that due to high tide during the site visit it was not possible to traverse much of the shoreline; therefore, photographs are limited but provide sufficient detail on the site conditions



This photograph was taken on the existing slipway facing west toward the Heritage Centre (orange arrow) and car park $34^{\circ}10'11.71''\text{S}$ $24^{\circ}50'1.05''\text{E}$
The boardwalk begins at the red arrow $34^{\circ}10'11.82''\text{S}$ $24^{\circ}50'0.66''\text{E}$



This photograph was taken facing a north-westerly direction $34^{\circ}10'11.98''\text{S}$ $24^{\circ}50'0.74''\text{E}$. This area is known as Granny's Pool. The entire route of the boardwalk along the shoreline is boulder strewn as is evident from all photographs.



This photograph shows the route of the boardwalk along the shoreline on the Granny's Pool side facing north-west $34^{\circ}10'11.61''\text{S}$ $24^{\circ}50'0.85''\text{E}$



This photograph facing north shows the route of the boardwalk up until approximately the middle point of the route (red arrow) $34^{\circ}10'11.49''\text{S}$ $24^{\circ}50'1.23''\text{E}$



This photograph shows a close-up of the middle section of the proposed boardwalk 34°10'11.49"S 24°50'1.23"E. The concrete retaining wall can be seen in the distance (start of retaining wall – orange arrow).



A close-up of the boulder strewn shoreline 34°10'11.49"S 24°50'1.23"E



This photograph was taken facing south and includes areas to the south-east and parts of south-west $34^{\circ}10'2.82''\text{S}$ $24^{\circ}49'54.46''\text{E}$. This photograph was taken at the proposed end of the boardwalk i.e. at the existing concrete retaining wall. This photograph shows the shoreline at high-tide. It is clear in this photograph that it is not safe to traverse this entire stretch of the shoreline at high-tide.