

DR. COLLEEN EBERSOHN
PhD Univ. Pretoria
Cell:072 222 6013

e-mail: ebersohn@cyberperk.co.za

MS. JANET EBERSOHN

Bsc. Hons. Environmental Management

Cell: 082 557 7122

e-mail: janet@ecoroute.co.za

## **APPENDIX D: SITE PHOTOGRAPHS**

## **Groot Dam (Construction):**

1. Aerial view of Groot Dam.



2. Area where dam wall was constructed.



3. Dam wall construction.




PO Box 3511, Knysna, 6570 www.ecoroute.co.za

4. Dam wall construction.



## **Groot Dam (Post-Construction):**



PO Box 3511, Knysna, 6570 www.ecoroute.co.za

5. Southwest view across dam from dam wall.



6. South view across dam from dam wall.



7. Dam slipway draining to wetland.



8. Access road to dam wall.



9. View across dam from western bank.



10. View of the western tributary into Groot Dam.



11. View across dam from southern bank.



12. View of the eastern tributary into Groot Dam.



13. View of the eastern tributary into Groot Dam.



15. Discarded rock in small stream next to the dam wall.



14. View from in the eastern tributary.

16. Discarded rock in small stream next to the dam wall.





1. Aerial view of Kop Dam.



2. View across dam from east to west.



3. View across dam from south to north.




PO Box 3511, Knysna, 6570 www.ecoroute.co.za

4. View across dam from west to east.



6. Solar panels on southern bank used to operate water pump.





7. View of the Kammanassierivier from Kop Dam.



8. Surrounding vegetation and cultivated land.



9. Surrounding vegetation and cultivated land.



