



SITE PHOTOGRAPHS (AFTER)

 <p>07 Sep 2017 10:11:20</p>	 <p>07 Sep 2017 10:16:35</p>
<p>1. Area where 100125m² vegetation was removed for the planting of Macadamia tree</p>	<p>2. Alien Vegetation along the river bank.</p>
 <p>07 Sep 2017 10:10:46</p>	 <p>07 Sep 2017 10:11:55</p>
<p>3. The area where the stream/river was straightened</p>	<p>4. Embankment Erosion</p>



5. Area of reconstructed dam wall